

Safety equipment

combi signs 12

N = 200 mm. R = 300 mm. Materials: R & V

 Danger Explosion risk In the event of fire remove bottles to safe area 120.001 NR	 Danger Explosion risk IMPORTANT Close all oxy/acetylene valves after each use 120.002 NR	 Warning Gas under pressure In case of fire remove cylinders to a safe place 120.005 NR	 Danger Vehicle fumes Ventilation to be in use at all times during cargo operations 120.006 NR	 Danger Gas No fire No open lights No smoking 120.007 NR
 Danger Non-ionizing radiation Secure radar, satcom and radio equipment before accessing the monkey island 120.010 NR	 Danger Confined space Do not enter without a permit to work 120.015 NR	 Danger Confined space Keep out 120.016 NR	 Danger Asbestos Do not disturb 120.017 NR	 Danger Hazardous area Do not enter 120.018 NR
 No smoking No naked lights 120.020 NR	 Do not throw garbage overboard Use bins provided 120.021 NR	 Danger Hazardous area No unauthorised entry 120.023 NR	 Danger Gas No fire No open lights No smoking 120.025 NR	

S = 400 mm. R = 300 mm. Materials: R & V

Machinery Space Caution Space protected by gas flood system if alarm sounds vacate immediately Machinery may start and stop without warning No entry to unauthorised personnel No smoking or naked lights except in designated areas Minimum safety requirements: Overalls Head protection Ear defenders Safety boots 120.050 RR	 Danger Explosion risk No smoking No naked lights No hot work No chipping No unapproved electrical equipment 120.051 RR	Refrigerated Space Caution Low temperature and slip hazard No smoking Wear hair net at all times 120.052 RR	Battery Locker Danger Battery acid No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Safety gloves Face shield 120.053 RR	Switch Gear Danger High voltage No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Safety gloves Ear defenders Safety boots 120.054 RR
Galley No smoking Wash hands before preparing food Minimum safety requirements: Hair net Safety footwear 120.055 RR	Gas Bottle Store Danger Compressed gases No entry to unauthorised personnel No smoking or naked lights Keep well ventilated 120.056 RR	Paint Store Danger Flammable Liquid No entry to unauthorised personnel No smoking or naked lights Keep well ventilated 120.057 RR	Emergency Generator Danger High voltage Machinery may start without warning No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Safety gloves Ear defenders Safety boots 120.058 RR	Forecastle Space Caution Space protected by gas flood system if alarm sounds vacate immediately Machinery may start and stop without warning No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Head protection Ear defenders Safety boots 120.059 RR
Fridge Machinery Danger Toxic fumes Machinery may start without warning No entry to unauthorised personnel No smoking or naked lights Keep well ventilated 120.060 RR	Steering Gear Danger Moving machinery No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Head protection Ear defenders Safety boots 120.061 RR	Pump Room Danger Confined space with moving machinery No entry to unauthorised personnel No smoking or naked lights Minimum safety requirements: Overalls Head protection Ear defenders Safety boots 120.062 RR	Security Notice Authorized access only No unauthorised weapons or photography Legal action will be taken on any violations 120.071 RR	Security Notice Permit to board required. Visitors must report to the Security Officer on arrival and departure. Baggage and personal searches may be conducted. No weapons, incendiary devices and explosives All mobile phones, pagers and other electronic equipment must be switched off or used in specified locations No photography 120.073 SR
 HAZARDOUS AREA FM 200 extinguishing system DO NOT enter unless system is isolated When alarm sounds or upon gas discharge evacuate area immediately After discharge DO NOT re-enter until thoroughly ventilated 120.074 RR	 HAZARDOUS AREA Carbon dioxide extinguishing system DO NOT enter unless system is isolated When alarm sounds or upon gas discharge evacuate area immediately After discharge DO NOT re-enter until thoroughly ventilated 120.075 RR	 HAZARDOUS AREA Halon 1301 extinguishing system DO NOT enter unless system is isolated When alarm sounds or upon gas discharge evacuate area immediately After discharge DO NOT re-enter until thoroughly ventilated 120.076 RR	Materials: R = Rigid Plast V = Self Adhesive Vinyl Size Codes: N = 200 mm. R = 300 mm. S = 400 mm.	